Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	37	wu-raymond.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 12:08
S3		348/372.ccls. and ((charging with battery).ti.)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2007/04/16 11:58
S4	0	348/372.ccls. and ((sensor with charging with battery).ab.)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON &	2007/04/16 11:59
S 5	0	348/372.ccls. and ((sensor and charging and battery).ab.)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 11:59
S6	2	"348"/\$ and ((sensor and charging and battery).ab.)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 12:00
S7	3	"250"/\$ and ((sensor and charging and battery).ab.)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 12:00
S8	2.	250/206.ccls, and ((sensor with charg\$3) with battery)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 12:10
S9		250/208.1.ccls. and ((sensor with charg\$3) with battery)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 12:11

S10	8	348/372.ccls. and ((sensor with charg\$3) with battery)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 12:45
S11	32	(CMOS and (sensor with coupled with (charg\$3 with battery)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ÓN	2007/04/16 12:56
S12	4	CMOS and ((image near3 sensor) with ((charging or charger) with battery))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 13:00
S13	2	348/372.ccls. and ((image near3 sensor) with ((charging or charger) with battery))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON ·	2007/04/16 13:03
S14	4	((image near3 sensor) with ((charging or charger) with battery)).ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 13:35
S15	43	((image with sensor) with ((charging or charger) with (battery or cell)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 14:28
S16	30	S15 and @ad<"20040324"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 13:42
S17	10	((image with sensor) with (battery adj charger))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 14:34

S18	5	((image adj sensor) with (battery adj charger))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:06
S19	325	(camera with (battery adj charger))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	·2007/04/16 14:38
S20	81	(camera with (battery adj charger)).ti.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 14:35
S21	66	S20 and @ad<"20040324"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON.	2007/04/16 14:37
S22	5	S20 and @ad<"20040324"	USPAT	OR	ON	2007/04/16 14:37
S23	17	348/372.ccls. and (battery adj charger)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2007/04/16 15:03
S24	15	S23 and @ad<"20040324"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 14:39
S25	216	"250"/\$ and (battery adj charger)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:03
S26	0	S25 and canera	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2007/04/16 15:04

S27	37	S25 and camera	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:04
S28	33	S27 and @ad<"20040324"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:04
S29	14	((image adj sensor) same (battery adj charger))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:07
S30	338	348/372.ccls:	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:46
S31	5	348/372.ccls. and (CMOS and charger)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2007/04/16 15:34
S32	7	CMOS and ((image adj sensor) with charger)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:37
S33	5	CMOS and ((image adj sensor) same (battery with charger))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:40
S34	17	"348"/\$ and ((image adj sensor) same (battery with charger))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ÓN	2007/04/16 15:41

4/18/2007 10:34:28 AM C:\Documents and Settings\kwang\My Documents\EAST\Workspaces\10808655.wsp Page 4

S35	288	348/372.ccls. and @ad<"20040324"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2007/04/16 15:48
S36 *	217	S35 and (battery or charger)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR.	ON * * *	2007/04/16 15:49
S37	15	S35 and (battery adj charger)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2007/04/16 15:49
\$38	20	S35 and (battery same charger)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:50
S39	217	S35 and (battery or charger)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:50
S40	24	S35 and (battery and charger)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:50
S41	24	S35 and (charger)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:55
S42	95	S35 and (battery with charg\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/04/16 15:59
S43	61	S35 and (battery with charg\$3)	USPAT	OR	ON	2007/04/16 16:20

1					0.0	- CN	2007/04/46 46-24
-	S44	2	S35 and (battery and charger and	USPAT	OR	ON	2007/04/16 16:21
			(image adj sensor))				